



00255011

WELL SITE INSPECTION

OPERATOR Union Texas Petro.

PERMIT NO _____

DATE _____

WELL NAME Ilife-Ertle 18-1COUNTY Logan

RIG _____

LEGAL NW S18 T9N R52W

SURFACE CSG SIZE _____ DEPTH _____

DATE _____

CEMENT VOLUME _____ RETURNS _____ WOC _____

PROBABLE FOX HILLS DEPTH & THICKNESS _____

MUD PITS _____

DISPOSAL _____

PROD STRING SIZE _____ DEPTH _____ CMT VOL _____ DATE _____

STAGED _____ CBL CHECKED _____

SQUEEZE _____ FRAC JOB _____

BATTERY _____ SIGN _____

PRESSURE CHECK _____ DATE _____

SITE INSPECTION AFTER DRILLING _____

7/30/86 Pump jack on well, producing well.Not plugged yet.

DIRECTIONS _____

ACTION _____

ENGINEER SP