

Inspection Photos
Location Name: Windsor 35-5
Location ID: 310283



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Windsor 35-5
Location ID: 310283



Photo 3: Centralized Tank Battery



Photo 4: Tank Battery; TANKS NOT ANCHORED, EARTH BERMES

Inspection Photos
Location Name: Windsor 35-5
Location ID: 310283



Photo 5: NO BBLs LABELED ON PRODUCED WATER, EARTH BERM, TANK NOT ANCHORED



Photo 6: Separator not anchored