

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-07246**  
**Date: 9-24-2019**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the southeastern edge facing northward. Revegetation is progressing with western wheatgrass, sand dropseed, and smooth brome.



Photo 3. View of erosion occurring on the northwestern project area. Significant sediment deposition observed down-slope. Bare soils on slope are not stabilized.



Photo 4. Downstream view of sediment accumulation in the northwestern project area.



Photo 5. View of reference area vegetation, comprised of mixed ponderosa pine and gambel oak woodland with grass field in openings.