

Inspection Photos

API: 05-071-09451

Operator: NATURAL RESOURCE GROUP

Inspection Date: 10/1/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09451 | Date: 10/1/2019

Inspection Photos



Photo 1. Facing north toward the location. There is various unused equipment at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09451 | Date: 10/1/2019

Inspection Photos



Photo 2. Facing northwest. There is an unused shed at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09451 | Date: 10/1/2019

Inspection Photos



Photo 3. There are barrels stored at the west side of the location. Labels are not legible and contents unknown. Hydrocarbon odor near the barrels with stained soils.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09451 | Date: 10/1/2019

Inspection Photos



Photo 4. Facing towards the storage tanks. The berm appears to be inadequate and there is dry vegetation around the tanks which is a fire hazard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09451 | Date: 10/1/2019

Inspection Photos



Photo 5. The sign at the well head does not display an emergency contact number, operator number, and public road description.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09451 | Date: 10/1/2019

Inspection Photos



Photo 6. There are barrels stored near the building at the center of the location. Labels are not legible and contents unknown. There is various unused equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09451 | Date: 10/1/2019