

Inspection Photos
Location Name: Carlson #1-24
Location ID: 321495



Photo 1 Well head sign and well head



Photo 2 TNK BTRY

Inspection Photos
Location Name: Carlson #1-24
Location ID: 321495



Colorado Oil and Gas Conservation Commission
Oct 2, 2019 13:08:05



Colorado Oil and Gas Conservation Commission
Oct 2, 2019 13:08:59

Photo 3 TNK BTRY

Photo 4 Can see where fence around TNK BTRY is rubbing on the ground from what appears to be the wind

Inspection Photos
Location Name: Carlson #1-24
Location ID: 321495



Photo 5 Can see where fence around TNK BTRY is rubbing on the ground from what appears to be the wind



Photo 6 Sep/ meter house fence

Inspection Photos
Location Name: Carlson #1-24
Location ID: 321495



Photo 7 sep/meter house



Photo 8 Can see where fence around sep/meter house is rubbing on ground from what appears to be the wind.