

Inspection Photos
Location Name: Great Western Pad 4
Location ID: 333028



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Great Western Pad 4
Location ID: 333028



Photo 3: WRONG wellhead sign



Photo 4: Wellhead

Inspection Photos
Location Name: Great Western Pad 4
Location ID: 333028



Photo 5: Tank Battery Sign



Photo 6: Tank Battery; Inadequate berms, tanks not anchored

Inspection Photos
Location Name: Great Western Pad 4
Location ID: 333028



Photo 7: No NFPA placard on H2O tank



Photo 8: Separator not anchored