

Inspection Photos
Location Name: Ruff 8-714
Location ID: 250569



Photo #1 Wellhead, No Well or Emergency contact information



Photo #2 Red "PTA" Variance Tag