

Inspection Photos
API#045-06239
Operator: Maralex
Inspection: #692401383
Inspection Date: 9/27/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to Southeast.

September 27, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Albertson Cattle Co. API#045-06239



Photo#2:
View over Blowdown Pit. Insert showing one area of damaged netting

September 27, 2019



Photo#3:
Area of damaged, gaped netting.

Photo#4:
Area of damaged, gaped netting.

September 27, 2019