

Inspection Photos
Operator: BP America
Location/API #: 067-07165
Date: 9-30-2019



Photo 1 View of the project area from the northern corner facing center.



Photo 2. View of the northern portion of the project area from the western edge facing northeastward. Fill slope appears stabilized with grasses such as smooth brome and young ponderosa pine and gambel oak trees.



Photo 3. View of straw wattle on the northern edge of the working area, full of sediment and no longer functional.



Photo 4. View of another straw wattle that is full of sediment and needs maintenance/repair.



Photo 5. View of reference area vegetation, comprised of ponderosa pine trees and gambel oaks.