

Inspection Photos  
Location Name: CATALINA 32-27  
API#: 05-071-08097  
INSP. #: 695101465



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos  
Location Name: CATALINA 32-27  
API#: 05-071-08097  
INSP. #: 695101465



**PHOTO 3: POLISH ROD PACKING IS LEAKING. COMPLY WITH  
1002 SERIES RULES AND 907 SERIES RULES. CA DATE 10-8-19**