

Inspection Photos

Location Name: Sater USX CC 19-23 Tank Battery

Location ID: 306177



Colorado Oil and Gas Conservation Commission
40.2938, -104.47575, 4644.6ft, 231°
10/08/2019 09:18:30 AM

Photo #1 Tank Battery

Inspection Photos
Location Name: Sater USX CC 19-23 Tank Battery
Location ID: 306177



Photo#2 Berm wall weathered



Photo #3 Berm wall weathered