

Inspection Photos

Location Name: SHIDELER G1SW

Location ID: 334069 & Spill/Release ID: 466951

Inspection Date: September 19, 2019




Photo #1 – Aerial view of the location. The green circle is around the lower tank battery, the blue oval is around the upper tank battery and the red area is the approximate excavation area.



Photo #2 – Location sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SHIDELER G1SW

Location ID: 334069 & Spill/Release ID: 466951

Inspection Date: September 19, 2019



Photo #3 – View of the rusted out bull plug in the lower tank battery.



Photo #4 – View of the hole in the lower tank battery liner.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SHIDELER G1SW

Location ID: 334069 & Spill/Release ID: 466951

Inspection Date: September 19, 2019



Photo #5 – View of the 5-6-inch hole and pen sized hole in a patch in the secondary containment liner of the upper tank battery.



Photo #6 – View of the stained gravel within the secondary containment of the upper tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SHIDELER G1SW

Location ID: 334069 & Spill/Release ID: 466951

Inspection Date: September 19, 2019



Photo #7 – View of the excavation looking south.



Photo #8 – View of the excavation looking east.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SHIDELER G1SW

Location ID: 334069 & Spill/Release ID: 466951

Inspection Date: September 19, 2019



Photo #9 – View of the stockpiled soil on the north side of the excavation.



Photo #10 – View of the right away located north of the location. The mentioned hole is located near the blue pipeline marker (blue circle).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SHIDELER G1SW

Location ID: 334069 & Spill/Release ID: 466951

Inspection Date: September 19, 2019



Photo #11 – View of the hole in the right away



Photo #12 – View of the hole in the right away.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SHIDELER G1SW

Location ID: 334069 & Spill/Release ID: 466951

Inspection Date: September 19, 2019



Photo #13 – View of subsidence on the right away.



Photo #14 – View of fluids in the arroyo and salt staining.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SHIDELER G1SW

Location ID: 334069 & Spill/Release ID: 466951

Inspection Date: September 19, 2019



Photo #15 – View of salt staining in the arroyo.



Photo #16 – View of salt staining and moist soil in the arroyo.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources