

Inspection Photos
Location Name: Doc Powell 30-14-11
Location ID: 330675



Photo 1 – Pumping Unit



Photo 2 – Tank Battery



Inspection Photos
Location Name: Doc Powell 30-14-11
Location ID: 330675



Photo 3 – Pit



Photo 4 – Stained Soil on north side of Pumping Unit

Inspection Photos
Location Name: Doc Powell 30-14-11
Location ID: 330675



Photo 5 – Stained Soil at Pumping Unit



Photo 6 – Stained Soil at Heater Treater

Inspection Photos
Location Name: Doc Powell 30-14-11
Location ID: 330675



Photo 7 – Stained Soil inside Heater Treater shed



Photo 8 – Stained Soil at West loadline bucket



Inspection Photos
Location Name: Doc Powell 30-14-11
Location ID: 330675




Photo 9 – East Tank missing NFPA Fire Diamond