

Texaco – Sullivan Mc(NCT-1)#1

API: 05-103-09258

Inspection: 679705733



Photo 1. Pump jack & propane tanks.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Texaco – Sullivan Mc(NCT-1)#1

API: 05-103-09258

Inspection: 679705733



Photo 2. Tanks & treater.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Texaco – Sullivan Mc(NCT-1)#1
API: 05-103-09258
Inspection: 679705733



Photo 3. Barrel.



Photo 4. Barrel & stained soil.

Texaco – Sullivan Mc(NCT-1)#1

API: 05-103-09258

Inspection: 679705733



Photo 5. Stained soil at pump jack.



Photo 6. Stained soil at pump jack.

Texaco – Sullivan Mc(NCT-1)#1

API: 05-103-09258

Inspection: 679705733



Photo 7. Tank label.