

# Seely Land & Livestock 1

API: 05-103-09250

Inspection: 679705735



40.201, -107.47338, 8045.0ft, 22°  
10/08/2019 02:53:15 PM

**Photo 1. Location.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Seely Land & Livestock 1**

**API: 05-103-09250**

**Inspection: 679705735**



**Photo 2. Tank battery.**





# Seely Land & Livestock 1

API: 05-103-09250

Inspection: 679705735



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Seely Land & Livestock 1  
API: 05-103-09250  
Inspection: 679705735



Photo 4. Tank label.



Photo 5. Chemical containers.



Seely Land & Livestock 1  
API: 05-103-09250  
Inspection: 679705735



Photo 6. Barrels next to pump jack.



Photo 7. Barrel next to propane tank.

Seely Land & Livestock 1  
API: 05-103-09250  
Inspection: 679705735



**Photo 8. Containers & stained soil in building.**



**Photo 9. Containers in building.**



**Seely Land & Livestock 1**  
**API: 05-103-09250**  
**Inspection: 679705735**



**Photo 10. Containers in building.**



**Photo 11. Stained soil at pump jack.**



Seely Land & Livestock 1  
API: 05-103-09250  
Inspection: 679705735



**Photo 12. Stained soil at pump jack.**



**Photo 13. Stained soil at tank.**