

Government Trinity 1
API: 05-103-09217
Inspection: 679705737



Photo 1. Location.



Government Trinity 1
API: 05-103-09217
Inspection: 679705737



Photo 2. Tank label.



Photo 3. Stained soil at pump jack.

Government Trinity 1
API: 05-103-09217
Inspection: 679705737



Photo 4. Stained soil at well head.