

Inspection Photos
Location Name: Open Range 18
Location ID: 447512



Photo 1. Overview of location taken at entrance facing northeast.



Photo 2. Equipment stored on location.

Inspection Photos
Location Name: Open Range 18
Location ID: 447512



Photo 3. Stained soil at wellhead.



Photo 4. Debris on location.