

*Inspection Photos*  
*API#s 045-09360, 09359*  
*Operator: Caerus*  
*Inspection Number: 692401416*  
*Inspection Date: 9/18/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Photo#1:**  
View of Location from entry to East.



**Photo#2**  
View of Location from center to East.

September 18, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus PAs Rowe API#s 045-09360, 09359





**Photo#3:**  
Riser and pipe fence remain on location.



**Photo#4:**  
Riser and pipe fence remain on location.

September 18, 2019





Photo#5:  
Access road & turnaround remain.




Photo#6:  
Access road & turnaround remain.

September 18, 2019





Photo#7:  
Weeds & bare areas.



Photo#8:  
Weeds & bare areas.

September 18, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus PAs Rowe API#s 045-09360, 09359





Photo#9:  
Weeds & bare areas.



Photo#10:  
Weeds & bare areas..

September 18, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus PAs Rowe API#s 045-09360, 09359





Photo#11:  
Weeds & bare areas.



Photo#12:  
Weeds & bare areas.

September 18, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus PAs Rowe API#s 045-09360, 09359