

Inspection Photos

Well 057-06490

Inspection Date: 10/9/2019

Photos taken by Kris Neidel



Photo #1 Sign at entrance from highway. Oper# and ph# are for previous operator.



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #2 entrance to location

Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #1 entrance to location



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #4 western fence of location, looking north

Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #5 stored equipment on location.

Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #6 stored equipment on location.



Inspection Photos

Well 057-06490

Inspection Date: 10/9/2019

Photos taken by Kris Neidel



Photo #7 stored equipment on location. East side of location.



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #8 tank



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #9 4 AGT's



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel

Photo #10 East side of tank battery



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #11 equipment on location.



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #12 inside tank battery



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #13 inside tank battery, oil stained soil.



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #14 line heater



Inspection Photos

Well 057-06490

Inspection Date: 10/9/2019

Photos taken by Kris Neidel



Photo #15 equipment note concrete pad to right of photo.



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #16 stored equipment/trash and building

Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #17 outside of building, note flare to left of photo



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel

Photo #18 outside of building



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #19 inside of building, treater.

Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #20 flare



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #21 flare with surface flowline

Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #22 wellhead



Inspection Photos

Well 057-06490

Inspection Date: 10/9/2019

Photos taken by Kris Neidel



Photo #23 close up of wellhead sign



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #24 wellhead



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #25 close up of wellhead



Inspection Photos  
Well 057-06490  
Inspection Date: 10/9/2019  
Photos taken by Kris Neidel



Photo #26 building at entrance to location



Inspection Photos

Well 057-06490

Inspection Date: 10/9/2019

Photos taken by Kris Neidel



Photo # 27 inside building at entrance to location. Building was empty with an open bottom.

