

# Inspection Photos

10/09/2019

Operator: FRITZLER RESOURCES INC - 31257

Location ID: 316908

Washington County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Operator Name: FRITZLER RESOURCES INC - 31257**  
**Location ID: 316908**



**Photo 1:** Photo taken from the south end of the pump unit, facing west. Photo shows equipment (pipe) not needed for production has not been removed from the location



**Photo 2:** Photo taken from the well, facing south. Photo shows stained soils have not been removed from wellhead. Area of contamination also appears to have expanded since previous inspection dated 5/20/2019.



Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 3:** See comments under photo2.



**Photo 4:** See comments under photo 2.



**Inspection Photos**  
**Operator Name: FRITZLER RESOURCES INC - 31257**  
**Location ID: 316908**



**Photo 5:** Photo taken from the north end of the pump unit, facing west. Photo shows equipment (pipe) not needed for production has not been removed from the location



**Photo 6:** Photo taken from the west end of the location. Photo shows equipment observed stored on the west end of the location has been removed.



**Inspection Photos**  
**Operator Name: FRITZLER RESOURCES INC - 31257**  
**Location ID: 316908**



**Photo 7:** Photo taken from the southwest (Southwest anchor). Photo shows trash debris, or equipment, remaining on location.



**Photo 8:** Photo taken from the southeast corner of the well location. Previous inspections required operator to comply with rule 1003 and mark anchors. Photo shows anchor on the southeast end of the location has not been marked in accordance with 1003 rules.



Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 9:** See comments under photo 8.



**Photo 10:** Previous inspections documented noxious weed establishment, and required operator to comply with Rule 1003.f.

Photo shows noxious weeds (Canada Thistle) remains established on location/pits.



Inspection Photos  
Operator Name: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 11:** See comments under photo 10.



**Photo 12:** See comments under photo 10.