

Inspection Photos

10/09/2019

Operator: ST CROIX OPERATING INC # 81490

Location ID: 466338

Washington County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: ST CROIX OPERATING INC # 81490
Location ID: 466338



Photo 1: Photo taken from the south end of the location, facing west. Photos 1-4 provide an overview of the location from west, northwest, northeast to east.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: ST CROIX OPERATING INC # 81490
Location ID: 466338



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.

Inspection Photos

Operator Name: ST CROIX OPERATING INC # 81490

Location ID: 466338



Photo 5: Photo taken from the topsoil stockpile on the west end of the location, facing east. Photo shows Operator has installed surface roughening (tracking) as a stabilization control on the slopes. Tracking has been installed along the contour of the slopes, rather than up and down. This will facilitate stormwater runoff and erosion degradation. BMP has not been installed in accordance with good engineering practices.



Photo 6: Photo from the topsoil stockpile on the west end of the location, facing west. See comments under photo 5.

Inspection Photos
Operator Name: ST CROIX OPERATING INC # 81490
Location ID: 466338




Photo 7: 2A Permit doc. #401779292 states size of disturbed area during construction to be 2.5 acres. On 10/09/2019, a disturbance area of 2.8 acres was mapped with a handheld Trimble GPS unit. Photo shows the mapped disturbance area. Operator appears to have exceeded the permitted disturbance area.

