

Inspection Photos

API: 05-017-07770

Operator: RESOURCE DEVELOPMENT

Inspection Date: 10/7/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-017-07770 | Date: 10/7/2019

Inspection Photos



Photo 1. Facing south at the center of the location. Crop has uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07770 | Date: 10/7/2019

Inspection Photos



Photo 2. Facing east at the center of the location. Crop has uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07770 | Date: 10/7/2019

Inspection Photos



Photo 3. Facing north at the center of the location. Crop has uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07770 | Date: 10/7/2019

Inspection Photos



Photo 4. Facing west at the center of the location. Crop has uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07770 | Date: 10/7/2019