

Inspection Photos

API: 05-017-07648

Operator: WIEPKING-FULLERTON ENERGY

Inspection Date: 10/7/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-017-07648 | Date: 10/7/2019

Inspection Photos



Photo 1. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07648 | Date: 10/7/2019

Inspection Photos



Photo 2. Facing west at the center of the location. There are areas that do not have adequate vegetation cover and there are undesirable weeds (Russian thistle).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07648 | Date: 10/7/2019

Inspection Photos



Photo 3. Facing southwest at the center of the location. There are areas that do not have adequate vegetation cover and there are undesirable weeds (Russian thistle).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07648 | Date: 10/7/2019

Inspection Photos



Photo 4. Facing north at the center of the location. There are areas that do not have adequate vegetation cover and there are undesirable weeds (Russian thistle).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07648 | Date: 10/7/2019

Inspection Photos



Photo 5. Facing south at the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07648 | Date: 10/7/2019