

Inspection Photos

API: 05-099-06198

Operator: CHURCHILL ENERGY

Inspection Date: 10/8/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-099-06198 | Date: 10/8/2019

Inspection Photos



Photo 1. Facing northeast toward the location. Tank remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-099-06198 | Date: 10/8/2019

Inspection Photos



Photo 2. Tank remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-099-06198 | Date: 10/8/2019