

**Inspection Photos**  
**Location Name: Beisel Unit #1**  
**Location ID: 319877**



**Photo 1 WH no sign**



**Photo 2 Guy line anchors not properly marked.**



**Inspection Photos**  
**Location Name: Beisel Unit #1**  
**Location ID: 319877**



**Photo 3 Weeds on location**



**Photo 4 Guy line anchors not properly marked.**

**Inspection Photos**  
**Location Name: Beisel Unit #1**  
**Location ID: 319877**



**Photo 5 Stained soil around WH**