

Inspection Photos
Location Name: PANTHER 33-5
API#: 05-071-09671
INSP. #: 695101509



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: PANTHER 33-5
API#: 05-071-09671
INSP. #: 695101511



PHOTO 3: WEEDS AROUND WELLHEAD AND SOUND WALLS.
COMPLY WITH RULE 603.f. CA DATE 10-18-19



PHOTO 4: UNUSED EQUIPMENT ON LOCATION (4" WATER HOSE).
COMPLY WITH RULE 603.f. CA DATE 10-18-19.