

Inspection Photos

API#077-08543

Operator: Caerus

Inspection Number: 6924014130

Inspection Date: 9/26/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources




Photo#1:
View over Location to South.



Photo#2:
Insert Thistle rosettes

September 26, 2019



Photo#3:
View East over Location.



Photo#4:
View West over Location.

September 26, 2019



Photo#5:
Insert of mature Musk thistle.

Photo#6:
Weedy area.

September 26, 2019