

Inspection Photos
Location Name: SPIKE 33-23
API#: 05-071-08704
INSP. #: 695101542



Colorado Oil & Gas Conservation Commission
37.2434, -104.96095, 2509.0m, 283°
2019/10/15 15:12:13

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.24339, -104.96159, 2528.0m, 301°
2019/10/15 15:12:52

PHOTO 2: WELL SIGN

Inspection Photos
Location Name: SPIKE 33-23
API#: 05-071-08704
INSP. #: 695101542



PHOTO 3: PIT LINER COMPROMISED. MAINTAIN PIT LINER AS PER RULE 904. CA DATE 11-15-19



PHOTO 4: PIT LINER IS DETERIORATING AROUND THE OUTER BERM AND SMALL PIECES OF LINER ARE BEING SPREAD AROUND LOCATION AND OFF SIGN. POLICE LOCATION AND SURROUNDING AREA FOR PIECES OF LINER. COMPLY WITH RULE 603.f. CA DATE 11-15-19