


**Inspection Photos**  
**Location Name: State 2**  
**Location ID: 310112**



**Photo 1 – Tank Battery**

**Photo 2 – Stained Soil at Wellhead**

**Inspection Photos**  
**Location Name: State 2**  
**Location ID: 310112**



Colorado Oil and Gas Conservation Commission  
40.65624, -104.20823, 4926.4ft, 255°  
10/08/2019 10:37:00



Colorado Oil and Gas Conservation Commission  
40.65627, -104.20817, 4928.1ft, 291°  
10/08/2019 10:33:19

**Photo 3 – Stained Soil at Engine**

**Photo 4 – Sucker Rods on the North side of the Pumping Unit**

**Inspection Photos**  
**Location Name: State 2**  
**Location ID: 310112**



**Photo 5 – Weeds at Heater Treater shed**

**Photo 6 – Weeds at Tank Battery**

**Inspection Photos**  
**Location Name: State 2**  
**Location ID: 310112**



Colorado Oil and Gas Conservation Commission  
40.65625, -104.20832, 4929 ft, 147°  
10/08/2019 10:34:10




Colorado Oil and Gas Conservation Commission  
40.65631, -104.20834, 4924 ft, 151°  
10/08/2019 10:33:50

**Photo 7 – Oily Waste and unused Chemical Containers at Pumping Unit**

**Photo 8 – Fence is in disrepair at wellhead**

**Inspection Photos**  
**Location Name: State 2**  
**Location ID: 310112**



**Photo 9 – Northeast Deadman anchor not marked**

**Photo 10 – Northwest Deadman anchor not marked**