

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/15/2019

Submitted Date:

10/16/2019

Document Number:

688306005**FIELD INSPECTION FORM**Loc ID 322194 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Grimes, Meghan		mgrimes@petrosharecorp.com	
Brown, Devin		dbrown@petrosharecorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209648	WELL	SI	06/01/2018	OW	039-06553	NORDMAN TRUST 41-20	TA

**General Comment:**[MIT Inspection, passed](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil at engine inside shed, non E&P waste.		
Corrective Action:	Remove and properly dispose of stained soil at engine.		Date: 11/15/2019

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:			
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 209648 Type: WELL API Number: 039-06553 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: TA because tank battery is decommissioned.

MIT Form 21 is attached.

0 psi on casing

0 min 500 psi

5 min 500 psi

10 min 500 psi

15 min 500 psi

0 psi on casing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Comment: -10 psi, took 50 secs to suck down

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688306009	Petroshare Nordman Trust 41-20 Rig 15 sign at CR	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4964598">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4964598</a>
688306010	Petroshare Nordman Trust 41-20 well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4964599">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4964599</a>
688306011	Petroshare Nordman Trust 41-20 wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4964600">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4964600</a>
688306012	Petroshare Nordman Trust 41-20 Form 21	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4964601">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4964601</a>