

Inspection Photos

Location Name: OUTPOST 22-24 TR FOLLOWUP

API#: 05-071-09193

INSP. #: 695101544



PHOTO 1: LOCATION




PHOTO 2: WELL SIGN

Inspection Photos

Location Name: OUTPOST 22-24 TR FOLLOWUP

API#: 05-071-09193

INSP. #: 695101544



Colorado Oil & Gas Conservation Commission
37.24596, -104.94777, 2434.0m, 316°
2019/10/16 12:00:01



Colorado Oil & Gas Conservation Commission
37.24596, -104.94777, 2434.0m, 258°
2019/10/16 12:00:12

PHOTO 3: AREA OF IMPACTED SOIL NEAR DRAIN ON ENGINE SKID FOR ORIGINAL WELL EQUIPMENT. IT APPEARS THAT A DRAIN ON UNIT IS BEING DRAINED ON THE GROUND.

IMMEDIATELY STOP DRAINING FLUIDS ON THE GROUND, Properly treat or dispose of oily waste in accordance with 907.e. CA DATE 11-16-19.

PHOTO 4: SEVERAL SPOTS OF IMPACTED SOIL BETWEEN ORIGINAL WELLHEAD AND ENGINE SKID. Properly treat or dispose of oily waste in accordance with 907.e. CA DATE 11-16-19.

Inspection Photos

Location Name: OUTPOST 22-24 TR FOLLOWUP

API#: 05-071-09193

INSP. #: 695101544



Colorado Oil & Gas Conservation Commission
37.2459, -104.94781, 2425.0m, 355°
2019/10/16 12:00:59

PHOTO 5: AREA OF IMPACTED SOIL AROUND COMPRESSOR SKID. Properly treat or dispose of oily waste in accordance with 907.e. CA DATE 11-16-19.



Colorado Oil & Gas Conservation Commission
37.2459, -104.94781, 2426.0m, 318°
2019/10/16 12:01:23

PHOTO 6: APPEARS TO BE STANDING OIL IN COMPRESSOR SKID CONTAINMENT. Comply with general provisions of the oil and gas act for wildlife protection.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: OUTPOST 22-24 TR FOLLOWUP

API#: 05-071-09193

INSP. #: 695101544



PHOTO 7: AREA OF IMPACTED SOIL AROUND TR WELLHEAD.
Properly treat or dispose of oily waste in accordance with 907.e. CA DATE 11-16-19.



PHOTO 8: AREA OF IMPACTED SOIL AROUND TR WELLHEAD.
Properly treat or dispose of oily waste in accordance with 907.e. CA DATE 11-16-19.

Inspection Photos

Location Name: OUTPOST 22-24 TR FOLLOWUP

API#: 05-071-09193

INSP. #: 695101544



PHOTO 9: LINER ON TR WELL PIT, THIS IS THE SECOND WARNING ON CORRECTIVE ACTION. SIGN AT WELLHEAD STATES PIT IS IN PROCESS FOR CLOSURE. PIECES OF LINER ARE BEING SPREAD AROUND LOCATION AND OFF SITE.
COMPLY WITH RULE 603.f. CONCERNING TRASH ON AND AROUND LOCATION, REMOVE SOURCE OF TRASH PREADING.