

Inspection Photos

API: 05-009-06017

Operator: WIGGS* GUY L

Inspection Date: 10/8/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06017 | Date: 10/8/2019

Inspection Photos



Photo 1. Facing east toward the location. The farmer has been farming around this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06017 | Date: 10/8/2019

Inspection Photos



Photo 2. There is cement and metal debris that remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06017 | Date: 10/8/2019

Inspection Photos



Photo 3. Facing back west at the area being farmed around do to debris remnants.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06017 | Date: 10/8/2019