

Inspection Photos
Location Name: Van Scoyk #1
Location ID: 320135




Photo 1 loc pic



Photo 2 loc pic

Inspection Photos
Location Name: Van Scoyk #1
Location ID: 320135



Photo 3 loc pic



Photo 4 red fuel gas line weather beaten and leaking

Inspection Photos
Location Name: Van Scoyk #1
Location ID: 320135



Photo 5 loc pic



Photo 6 loc pic

Inspection Photos
Location Name: Van Scoyk #1
Location ID: 320135



Photo 7 loc pic



Photo 8 loc pic

Inspection Photos
Location Name: Van Scoyk #1
Location ID: 320135



Colorado Oil and Gas Conservation Commission
Oct 17, 2019 11:40:45

Photo 9 loc pic



Colorado Oil and Gas Conservation Commission
Oct 17, 2019 11:42:37

Photo 10 TNK BTRY

Inspection Photos
Location Name: Van Scoyk #1
Location ID: 320135



Photo 11 loc pic

Photo 12 loc pic