

Inspection Photos
Location Name: Ehler-61S67W/4SESE
Location Number: 320460



Photo 1: Track-out control mat and perimeter fence gate.



Photo 2: Spoil pile. Wattles have been deployed at some places inside the perimeter fence, but do not cover the entire perimeter.

Inspection Photos
Location Name: Ehler-61S67W/4SESE
Location Number: 320460



Photo 3: Spoil pile without storm water BMPs.



Photo 4: Spoil Pile without storm water BMPs.

Inspection Photos
Location Name: Ehler-61S67W/4SESE
Location Number: 320460



Photo 5: Ground water has infiltrated open excavation.



Photo 6: Open excavation.

Inspection Photos
Location Name: Ehler-61S67W/4SESE
Location Number: 320460



Photo 7: Temporary piezometers outside of the perimeter fence in wetland adjacent to north side of disturbed area.



Photo 8: Temporary piezometer outside of the perimeter fence in wetland adjacent to north side of disturbed area.