

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/09/2019

Submitted Date:

10/17/2019

Document Number:

689501012

FIELD INSPECTION FORM

Loc ID 322581 Inspector Name: Oakman, Kari On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10311
Name of Operator: SRC ENERGY INC
Address: 1675 BROADWAY SUITE 2600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspections@srcenergy.com	ALL INSPECTIONS
Graber, Nikki		nikki.graber@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243887	WELL	PR	09/01/2018	OW	123-11679	KINDSFATER #23-13	EI

General Comment:

COGCC Environmental Inspection to determine the status of pit facility ID 111031. Pit location was determined based on aerial imagery. Stunted vegetation was present at the historic pit location. Operator is instructed to submit a Form 27 for site characterization of the historic pit area.

Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site condition at the time of inspection.

Inspected Facilities

Facility ID: 243887 Type: WELL API Number: 123-11679 Status: PR Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Pit location was determined based on aerial imagery (photos 7-11). Stunted vegetation was present at the historic pit location (photos 5&6).

Corrective Action: Operator shall submit a Form 27 Site Investigation and Remediation Workplan for site characterization of the historic pit area. Date: 11/09/2019

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
Contact area EPS Nikki Graber with any questions regarding Form 27 Submittal.	oakmank	10/17/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689501013	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4966133