

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 1 – Pumping Unit, Stained Soil at Wellhead

Photo 2 – Tank Battery

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 3 – Stained Soil at Wellhead

Photo 4 – Stained Soil at Engine Exhaust

Inspection Photos
Location Name: Hahn 1-4H
Location ID: 424891



Photo 5 – Stained Soil at Engine