

Inspection Photos
Location Name: Jillson A #4
Location ID: 319024



Colorado Oil & Gas Conservation C
40.12312, -105.00153, 48
10/17/20



Colorado Oil & Gas Conservation C
40.1223, -105.00118, 4
10/17/20

Photo #1 weeds overgrown on access road

Photo #2 WH sign

Inspection Photos
Location Name: Jillson A #4
Location ID: 319024



Photo #3 PU weeds overgrown on location

Photo #4 weeds growing around WH

Inspection Photos
Location Name: Jillson A #4
Location ID: 319024



Photo #5 Weeds overgrown around Electric panel, transformers and meter box.

Photo #6 unused deadman anchor.

Inspection Photos
Location Name: Jillson A #4
Location ID: 319024



Photo #7 Weeds overgrown around Electric panel, transformers and meter box.

Photo #8 weeds around PU.