

Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441



Photo 1 – Pumping Unit



Photo 2 – Tank Battery



Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441




Photo 3 – Stained Soil at Wellhead, Stuffing Box appears to be leaking. Wellhead Sign does not reflect current Operator.




Photo 4 – Stained Soil at Chemical Tank. Install wildlife netting on Containment



Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441



Photo 5 – Oily Waste, trash and debris inside containment.



Photo 6 – Oily Waste and debris inside Containment. Install wildlife netting on Containment

Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441




Photo 7 – Stained Soil at Day Barrel.



Photo 8 – Unused equipment and Unused Rods



Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441



Photo 9 – Unused Tubing in Northeast corner on location.




Photo 10 – Unused equipment – 2-Phase, and 2” piping



Inspection Photos
Location Name: Ford Family Trust 2H
Location ID: 428441



Photo 11 – Oily waste, trash inside containment, install Wildlife netting.



Photo 12 – Stained Soil at the Dump inside the Heater Shed

