

Interim Reclamation and Stormwater Inspection

October 15, 2019

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 456151

Inspection Document #: 697500719

Weld County, CO

Lot 2 Section 31 T7N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Hester Farms II /31-H Pad
Location ID: 456151



Photo 1. Photo taken on October 15, 2019 from the pit area, facing South. Photo illustrates the general location (red circle) of the wildlife bird mortality that still remains after approximately one month since discovery by COGCC staff.

Inspection Photos
Location Name: Hester Farms II /31-H Pad
Location ID: 456151



Photo 2. Close up photo taken on October 15, 2019 from the pit area illustrating the wildlife bird mortality that still remains.

Inspection Photos
Location Name: Hester Farms II /31-H Pad
Location ID: 456151



Photo 3. Photo taken on October 15, 2019 from the adjacent pit area, facing West. Photo illustrates the current BMPs which were also in place during the September 17, 2019 inspection.

Note: Operator has haphazardly installed safety fencing around portions of the pit area.

Inspection Photos
Location Name: Hester Farms II /31-H Pad
Location ID: 456151



Photo 4. Photo taken on October 15, 2019 from the adjacent pit area, facing East. See comments under Photo 3.

Inspection Photos
Location Name: Hester Farms II /31-H Pad
Location ID: 456151



Photo 5. Photo taken on September 17, 2019 from the pit area illustrating a wildlife bird mortality.