

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 1. Overview of location taken facing south.



Photo 2. Equipment and debris on location.

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 3. Equipment, debris, stained soil on location.



Photo 4. Equipment and debris on location, unmarked risers on left side of photo.

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 5. Equipment and debris on location.



Photo 6. Equipment and debris on location.

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 7. Equipment and debris on location.



Photo 8. Equipment and debris on location.

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 9. Weeds and vegetation on battery berm.



Photo 10. No wellhead sign, pump jack stored on location.

