

Inspection Photos
Location Name: Surprise Central Facility
Location ID: 436676



Photo 1. Overview of location facing southwest.



Photo 2. Example of stained soil on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources