

**Inspection Photos**  
**Location Name: Chalk 31-13**  
**Location ID: 413187**



**Photo 1 – Pumping Unit**



**Photo 2 – Tank Battery – Crude Oil & Produced Water tanks are in poor paint condition. Refer to Rule 804**

**Inspection Photos**  
**Location Name: Chalk 31-13**  
**Location ID: 413187**



**Photo 3 – Pit**



**Photo 4 – Stained Soil at the West loadline valve**

**Inspection Photos**  
**Location Name: Chalk 31-13**  
**Location ID: 413187**



**Photo 5 – Stained Soil at Pumping Unit**