

Inspection Photos
Operator: Kinder Morgan
Location/API #: 083-06726
Date: 10-11-2019



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area where young grasses such as western wheatgrass are becoming established.



Photo 3. View of erosional rilling and sediment deposition along access roadside.



Photo 4. View of reference area vegetation comprised of mixed field and sagebrush shrubland.