

# *Inspection Photos*

*API#103-07980*


*Operator: Utah Gas Corp*

*Inspection Number: 692401468*

*Inspection Date: 10/8/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
View Northwest.



Photo#2:  
View Southeast.

October 8, 2019





Photo#3:  
Weedy Meter house area.



Photo#4:  
Weedy Meter house area.

October 8, 2019





Photo#5:  
Exclusion fence line between reclaim and grazed pasture.

October 8, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Utah Gas PA Superior-Fee API#103-07980