

Inspection Photos  
Location Name: Spike State CC 6-11J  
API ID: 123-07639



Photo #1 Well, Sign, Weeds & Tore down fence

Photo #2 Variance tag & Weeds