

# Final Reclamation Inspection

October 17, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 330604

Inspection Document #: 697500746

Weld County, CO

SWNE Section 16 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: STATE BEATRICE #32-16  
Location ID: 330604



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates the well location has not been properly re-contoured to match the surrounding landscape and/or potential subsidence occurred.

Inspection Photos  
Location Name: STATE BEATRICE #32-16  
Location ID: 330604



**Photo 2.** Photo taken from the tank battery location, facing South. Appears a recent disturbance has taken place and crop have already been harvested; therefore, COGCC staff could not make a vegetative assessment.

Inspection Photos  
Location Name: STATE BEATRICE #32-16  
Location ID: 330604



**Photo 3.** Photo taken from the tank battery location, facing Southeast. See comments under Photo 2.