

Inspection Photos

Location Name: North Platte 44-11-28HZ /Facility

Location #: 331805



Colorado Oil & Gas Conservation Commission
40.36093, -104.43381, 1370.0m, 23°
10/21/2019 03:49:13 PM

Photo #1

DOW 41-33 (05-123-21329) Wellsite

Plugged & Abandoned | PA

Improper Abandonment of flowline | NOT LOTO



Colorado Oil & Gas Conservation Commission
40.36143, -104.43465, 1365.0m, 167°
10/21/2019 04:06:56 PM

Photo #2

North Platte 44-11-28HZ Battery

Shut-down | Inactive

DOW 41-33 well formerly connected to Battery