

Inspection Photos
Location Name: Hamil 19-16HA
Location ID: 442178



Photo 1. Overview of location taken facing southwest.



Inspection Photos
Location Name: Hamil 19-16HA
Location ID: 442178



Photo 2. Tubing stored adjacent to pump jack.



Photo 3. Bucket at exhaust with stained soil around it.

Inspection Photos
Location Name: Hamil 19-16HA
Location ID: 442178



Photo 4. Rills and sediment leaving location.



Photo 5. Rills and sediment leaving location.

