

Inspection Photos

Location Name: McIntyre Flowback Pits #3 and #4

Facility ID: 421066



Bird deterrent pennants are sagging into contents of lower pit.



Previously repaired area in lower pit netting.




Inspection Photos

Location Name: McIntyre Flowback Pits #3 and #4

Facility ID: 421066



Close up of previously repaired area in lower pit netting.



New holes in netting of lower pit.

