

Final Reclamation Inspection

October 17, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 310710

Inspection Document #: 697500756

Weld County, CO

SENW Section 15 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SENA #15-24
Location ID: 310710



Photo 1. Photo taken from the tank battery location, facing South. There appears to be a lack of crop growth throughout portions of the tank battery.

Inspection Photos
Location Name: SENA #15-24
Location ID: 310710



Photo 2. Photo taken from the tank battery location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: SENA #15-24
Location ID: 310710



Photo 3. Reference photo taken east of the tank battery location, facing North. Photo illustrates the vegetative difference from a reference crop area vs the lack of growth observed at the tank battery.

Inspection Photos
Location Name: SENA #15-24
Location ID: 310710



Photo 4. Photo taken from the well location access road, facing North. Operator has failed to remove the access point and culvert.

Inspection Photos
Location Name: SENA #15-24
Location ID: 310710



Photo 5. Photo taken from the well location access road, facing East. Well location and well location access road, minus the access point, appear reflective of reference areas.